

# Earthshots

Isahaya Bay, Japan



## Isahaya Bay, Japan 1993-2010

The controversial Isahaya Bay Reclamation Project has been blamed for recent reduced harvests of fish and seaweed (nori). The 1993 image shows the bay before a sea wall was built. In the 2010 image, reclaimed land extends into the area lying behind the 7-km (4-mile) wall.

Date	Satellite	Bands	Res	Path	Row
May 15, 1993	Landsat 5 TM	7,5,3	30 m	113	37
Sept. 3, 2010	Landsat 5 TM	7,5,3	30 m	113	37

### Earthshots: Satellite Images of Environmental Change

The U.S. Geological Survey Earth Resources Observation and Science (EROS) Center archives data from the Landsat satellites (1972–present). Earthshots presents environmental changes using Landsat images.

